



Bulkhead SSKK



G	h		SW		Order No.	
	mm	in	mm	in	NBR (BUNA)	FPM (VITON) (Standard)
S 12	63	2.48	19	0.75	SSKK 12-P	SSKK 12-V

TEST


Gauge Adaptor SMA



G	h		SW		Order No.	
	mm	in	mm	in	NBR (BUNA)	FPM (VITON) (Standard)
G 1/4	51	2.00	19	0.75	SMA 12 - G 1/4 - P-OR	SMA 12 - G 1/4 - V-OR
G 1/2	61	2.40	27	1.06	SMA 12 - G 1/2 - P-OR	SMA 12 - G 1/2 - V-OR
1/4 NPT	51	2.00	19	0.75	SMA 12 - 1/4 NPT-P	SMA 12 - 1/4 NPT-V
1/2 NPT	61	2.40	27	1.06	SMA 12 - 1/2 NPT-P	SMA 12 - 1/2 NPT-V

Snubber on request


Direct Gauge Adaptor SMD



G	h		SW		Order No.	
	mm	in	mm	in	NBR (BUNA)	FPM (VITON) (Standard)
G 1/4	35	1.38	19	0.75	SMD 12 - G 1/4 - P-OR	SMD 12 - G 1/4 - V-OR
G 1/2	45	1.77	27	1.06	SMD 12 - G 1/2 - P-OR	SMD 12 - G 1/2 - V-OR
1/4 NPT	35	1.38	19	0.75	SMD 12 - 1/4 NPT-P	SMD 12 - 1/4 NPT
1/2 NPT	45	1.77	27	1.06	SMD 12 - 1/2 NPT-P	SMD 12 - 1/2 NPT

Snubber on request

Swivel Run Tees SGV



Order Code Without Test Point									
Thread G	Ød1	Ød1	l1	l2	l3	l4	Hex1	Hex2	Order No.
	mm	in	mm	mm	mm	mm	mm	mm	
7/16 - 20 UNF	7.49	4.9	9	14	37	8	27	17	SGV 7/16 UNF - 04 - JIC 1/4 F/M
9/16 - 18 UNF	11.05	8.08	10.5	14.1	37.6	8.5	27	19	SGV 9/16 UNF - 06 - JIC 3/8 F/M
3/4 - 16 UNF	14.48	10.82	10.5	16.7	48.7	8.5	27	22	SGV 3/4 UNF - 08 - JIC 1/2 F/M

Order Code Including Test Point (SKK 12 - 7/16 UNF - VE)									
SKK 12 - 04 - JIC 1/4 - F/M-1137									
SKK 12 - 06 - JIC 3/8 - F/M-1137									
SKK 12 - 08 - JIC 1/2 - F/M-1137									

Other threads available upon request.