


Tester Overview



Rechargeable Battery Operation	-	●	●	●	●	●
Battery Operation	●	-	-	-	-	-
Automobile Adaptor	-	○	○	○	○	○

Number of Sensor Inputs	2	2	2	3	4	6
PC Interface RS-232	-	-	●	-	-	●
PC Interface USB	-	-	-	●	●	-
Online Function	-	-	●	●	●	●
Extended Data Memory - 1 Mio.	-	-	-	●	●	-
Programming of Automatic Measuring Tasks	-	-	-	●	●	-
Internal Trigger Function	-	-	-	●	●	●
Data Display	●	●	●	●	●	●
Graphic Display	-	-	-	●	●	●
Display Lighting	-	-	-	●	●	-
Curve Printout	-	-	-	●	●	●
PC Software Kit	-	-	○	●	●	●

Pressure Measurement	●	●	●	●	●	●
Temperature Measurement	●	●	●	●	●	●
Flow Measurement	●	●	●	●	●	●
Rotational Speed Measurement	●	●	●	●	●	●
Frequency Measurement	-	-	-	●	●	●
External Trigger Function	-	-	-	●	●	●
Third-party Sensors	-	-	-	●	●	●
Current/Voltage Adaptor	-	-	-	●	●	●

○ = Optional, ● = Standard, - = not available